


NEW JERSEY STATE HIGHWAY ROUTE NO. 206  
**PLAN**



NOTE: ALL SEAL COAT TO BE REJUVENATE  
 AND CRACK SEAL MATERIAL TO BE APPROVED  
 BY OWNER

SEAL COAT/CRACK SEAL AND RESTRIPE  
 SEAL COAT TOTAL = 1,140 SY  
 POT HOLE REPAIR, SEAL COAT, CRACK SEAL  
 AND RESTRIPE = 2,625 SY  
 POT HOLE REPAIR = 550 SY (INCL. 90 SF MISC.)

**PAYMENT IMPROVEMENT PLAN**

| NO. | DESCRIPTION | DATE | APPROVED BY | DATE |
|-----|-------------|------|-------------|------|
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |
|     |             |      |             |      |

ROBERT C. SHUBAR  
 RESTARACH PARK  
 BLOCK 35001, LOTS 10-15  
 MONTICMERY TOWNSHIP, SOMERSET COUNTY, NJ  
 HILTON MANAGEMENT, L.L.C.  
 1000 HILTON DRIVE  
 FORT LEE, NJ 07024  
 PROJECT NO. 2014-0550  
 DATE: APR 25, 2014 PAVING 2014 1 of 1